

Magnetic Clamping Kits: ¼-20 Thread



Part Numbers	Description	R20-MCK-A	R20-MCK-B	R20-MCK-C
R20-50-M	1/2" Dia. Magnet	3	4	6
R20-75-M	3/4" Dia. Magnet	3	4	6
R20-1-M	1" Dia. Magnet	3	4	6
R20-50-PM	1/2" Dia. Pin Magnet		2	2
R20-75-PM	3/4" Dia. Pin Magnet			2
R20-37550-SO	3/8" Dia. x 1/2" Standoff		3	4
R20-5050-SO	1/2" Dia. X 1/2" Standoff			4
R20-5075-SO	1/2" Dia. X 3/4" Standoff	3	6	8
R20-501-SO	1/2" Dia. X 1" Standoff	3	6	8
R20-502-SO	1/2" Dia. X 2" Standoff	3	6	8
R20-7550-SO	3/4" Dia. X 1/2" Standoff		3	4
R20-7575-SO	3/4" Dia. X 3/4" Standoff	3	6	8
R20-751-SO	3/4" Dia. X 1" Standoff	3	6	8
R20-752-SO	3/4" Dia. X 2" Standoff	3	6	8
R20-754-SO	3/4" Dia. X 4" Standoff		3	6
R20-175-SO	1" Dia. X 3/4" Standoff	3	6	8
R20-11-SO	1" Dia. X 1" Standoff	3	6	8
R20-12-SO	1" Dia. X 2" Standoff	3	6	8
R20-14-SO	1" Dia. X 4" Standoff		3	6
R20-ST3-3	Small Tension Spring - 3" Post	4		
R20-ST3-15	Small Tension Spring - 15" Post		4	4
R20-LT3-3	Large Tension Spring - 3" Post		8	8
R20-XLT3	X-Large Tension Spring - 3" Post			2
R20-1-TSB	1" Dia. Tension Spring Bracket			1
R20-NC	Nylon Cone	3	4	6
R20-SRP	Steel Resting Pin		4	6
R20-APJ	Adjustable Pivot Joint			1
R20-50-JS	1/2" Dia. Jackstand	1	2	3
R20-1-JS	1" Dia. Jackstand		2	3
R20-MSLD	Mini Slide Base	1	2	3
R20-SLD	Slide Base	1	2	3
R20-LB	Locating Block with Base		2	2
R20-112-MT4	1" Sq. x 12" Mini Tower			1
R20-SCT	1/4-20 Small Component Tray	1	1	2
Total Components		47	111	163