

Magnetic Clamping Kits: M8 Thread



Part Numbers	Description	R8-MCK-A	R8-MCK-B	R8-MCK-C
R8-13-M	13mm Dia. Magnet	3	4	6
R8-19-M	19mm Dia. Magnet	3	4	6
R8-25-M	25mm Dia. Magnet	3	4	6
R8-13-PM	13mm Dia. Pin Magnet		2	2
R8-19-PM	19mm Dia. Pin Magnet			2
R8-1315-SO	13mm Dia. X 15mm Standoff		3	3
R8-1320-SO	13mm Dia. X 20mm Standoff	3	6	8
R8-1325-SO	13mm Dia. X 25mm Standoff	3	6	8
R8-1350-SO	13mm Dia. X 50mm Standoff	3	6	8
R8-1915-SO	19mm Dia. X 15mm Standoff		3	3
R8-1920-SO	19mm Dia. X 20mm Standoff	3	6	8
R8-1925-SO	19mm Dia. X 25mm Standoff	3	6	8
R8-1950-SO	19mm Dia. X 50mm Standoff	3	6	8
R8-19100-SO	19mm Dia. X 100mm Standoff		4	6
R8-2520-SO	25mm Dia. X 20mm Standoff	3	6	8
R8-2525-SO	25mm Dia. X 25mm Standoff	3	6	8
R8-2550-SO	25mm Dia. X 50mm Standoff	3	6	8
R8-25100-SO	25mm Dia. X 100mm Standoff		4	6
R8-STS-38	Small Tension Spring - 38mm Post		4	4
R8-LTS-75	Large Tension Spring - 75mm Post	3	8	8
R8-XLTS	X-Large Tension Spring - 75mm Post			2
R8-25-TSB	25mm Dia. Tension Spring Bracket			1
R8-NC	Nylon Cone	3	4	4
R8-SC	Steel Cone		4	4
R8-PJ	Pivot Joint			1
R8-19-JS	19mm Dia. Small Jackstand	1	2	3
R8-25-JS	25mm Dia. Large Jackstand		2	3
R8-SLD	Slide Base	1	3	5
R8-LB	Locating Block with Base		2	2
R8-25300-MT4	25mm Sq. X 300mm Mini Tower			1
R8-SCT	M8 Small Component Tray	1	1	2
Total Components		45	112	152