



Standoffs Continued



Part Number	Thread	A	B
R6-19150-SO	M6	19 mm	150 mm
R6-2520-SO	M6	25 mm	20 mm
R6-2525-SO	M6	25 mm	25 mm
R6-2550-SO	M6	25 mm	50 mm
R6-25100-SO	M6	25 mm	100 mm
R6-25125-SO	M6	25 mm	125 mm
R6-25150-SO	M6	25 mm	150 mm
R4-65-SO (No female thread)	M4	6 mm	5 mm
R4-610-SO (No female thread)	M4	6 mm	10 mm
R4-620-SO (No female thread)	M4	6 mm	20 mm
R4-625-SO (No female thread)	M4	6 mm	25 mm
R4-95-SO (No female thread)	M4	9 mm	5 mm
R4-910-SO	M4	9 mm	10 mm
R4-920-SO	M4	9 mm	20 mm
R4-925-SO	M4	9 mm	25 mm
R4-125-SO (No female thread)	M4	12 mm	5 mm
R4-1210-SO	M4	12 mm	10 mm
R4-1220-SO	M4	12 mm	20 mm
R4-1225-SO	M4	12 mm	25 mm

Pin Standoffs



Part Number	Thread	A	B	C	D
R20-2525-PSO	1/4-20	0.25"	0.25"	0.062"	0.15"
R20-2550-PSO	1/4-20	0.25"	0.50"	0.062"	0.15"
R20-251-PSO	1/4-20	0.25"	1"	0.062"	0.15"
R20-37525-PSO	1/4-20	0.375"	0.25"	0.062"	0.15"
R20-37550-PSO	1/4-20	0.375"	0.50"	0.062"	0.15"
R20-3751-PSO	1/4-20	0.375"	1"	0.062"	0.15"
R20-5025-PSO	1/4-20	0.50"	0.25"	0.062"	0.15"
R20-5075-PSO	1/4-20	0.50"	0.75"	0.125"	0.15"
R20-501-PSO	1/4-20	0.50"	1"	0.125"	0.15"
R20-7575-PSO	1/4-20	0.75"	0.75"	0.125"	0.15"
R20-175-PSO	1/4-20	1"	0.75"	0.125"	0.15"
R20-11-PSO	1/4-20	1"	1"	0.125"	0.15"
R8-1320-PSO	M8	13 mm	20 mm	3.2 mm	3.8 mm
R8-1325-PSO	M8	13 mm	25 mm	3.2 mm	3.8 mm
R8-1920-PSO	M8	19 mm	20 mm	3.2 mm	3.8 mm
R6-1320-PSO	M6	13 mm	20 mm	3.2 mm	3.8 mm
R6-1325-PSO	M6	13 mm	25 mm	3.2 mm	3.8 mm
R6-1920-PSO	M6	19 mm	20 mm	3.2 mm	3.8 mm
R6-1925-PSO	M6	19 mm	25 mm	3.2 mm	3.8 mm
R6-65-PSO	M6	6 mm	5 mm	2 mm	3.8 mm
R6-610-PSO	M6	6 mm	10 mm	2 mm	3.8 mm
R6-625-PSO	M6	6 mm	25 mm	2 mm	3.8 mm
R6-95-PSO	M6	9 mm	5 mm	2 mm	3.8 mm
R6-910-PSO	M6	9 mm	10 mm	2 mm	3.8 mm
R6-925-PSO	M6	9 mm	25 mm	2 mm	3.8 mm